

uctions and Sign In Sheet

Safety Items

- Bump MG sets don't bar them over for lubrication
- Save some ribs.
- LOTO make sure disconnect is in locked position when mechanics applied locks it could still be operated. Fixed their procedures. Re looking @ all their procedures
- Reviewed the backfed fatality @ Kayenta it's on MSHA's website
- Some mines have removed on board temporary generators gone to transfer mtded
- many MSHA fatalities recent have been
- welding related working O/H setting string on chat
- use a non contact wand to help detect unknown V sources example shorted 120vac thermistor emergency stop causing a shock (added LOTO)
- Redbody issued ~~check~~ on V indicators
- Insurance Co's and mines with Plants that adhere to OSHA have been pushing A-Flash Awareness
- Human Performance Initiatives like a Job Hazard Analysis have helped recognize areas for improvement

NAME & COMPANY	
David Barrett	DCS
Glenn Simpson	Luminant
David Barrett	DCS
Glenn Simpson	Luminant
	(added LOTO)

New Innovations and Technology

- Kiewit San Miguel uses std form for most jobs
- Blank one for non-std jobs (help identify concerns/unknown hazards)
- DCS completed upgrade to Siemens
- GRA 80 series operators reported machine felt more responsive
- Coleman is upgrading an 8750 to Conforma in Rec

NAME & COMPANY	
Kiewit San Miguel	Westley Reed
Woody Vowell	Red Hill Mine

## Problems and Solutions

	NAME & COMPANY
Clean 8750 restarted machine had ruined one drive they replaced and thought they had parameter backwards < Payout = Pay in > fixed on app out.	Cotencu Channing Hatzelbuehler
Print was opposite to the real terminal fixed the print	
HPI - good after job to review + suggest improvements	
best if managers + directors read those Post job analysis	
DCS starting to use Australia's method of doing Pao + Post dragline performance XY + current readings as compared much better method	

## Future Meeting Topics

	NAME & COMPANY
LOTO maybe future present on committee findings	Donnie Heymer was on the Laminat Committee
Grinding - gravel roads + plates what does your local MSHA inspector say?	Glenn Simpson volunteered Donnie :)

## Future Locations

	NAME & COMPANY
- Fort Worth maybe with a mine team to show off cable reeler	
- a Laminat	
Billings had good turn out.	

# Group Sign In Sheet

Name	Company
1. Jeff Glenney	Littell Starco
2. Mike McCabe	Southwest
3. Glenn Simpson	Luminant
4. David Barrett	DCS
5. Auster John	Liberty Mine
6. Skip Venzel	AZ Elec Apparatus
7. CHANNING HATZENBUHLER	COTEAU PROPERTIES
8. Wesley REED	Kiewit - SAN MIGUEL MINE
9. Woody Vanzell	Red Hills Mine
10. Billy Hood	Red Hills mine
11. Terry W. Miller	Red Hills Mine
12.	
13.	
14.	
15.	
16.	
17.	
18.	
19.	
20.	

## Additional Comments

Additional Comments	NAME & COMPANY